



April 16, 2021

Subject: Supply Disruption Polar Vortex impacted BONDERITE® AERO products

Dear Valued Customer,

The recent weather events in Texas and along the Gulf Coast have caused severe supply chain disruptions. These disruptions have limited the ability of Henkel Corporation ("Henkel") to procure raw materials needed for the products listed below. Due to these unforeseen circumstances, Henkel is in the process of reviewing its ability to fill existing orders and will need additional time to confirm recent orders.

We are in close contact with our suppliers during this very complex and rapidly evolving situation and using all commercially reasonable means to address this situation and support our customers.

Your account manager will contact you to discuss the status of current and future orders. Henkel appreciates your patience and understanding during this challenging period.

Sincerely,

George Thomas, VP Regional SBU Head Industrials America's

Impacted Product List:

BONDERITE M-CR 1132 AERO
BONDERITE M-CR 871 AERO
BONDERITE M-CR 120 BRUSH AERO
BONDERITE C-IC 33 AERO
BONDERITE M-CR 1001 AERO
BONDERITE M-CR MAGNESIUM AERO

